

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 - 1970)

Name of the School

: St. Paul's Public school Kuriachira, Thrissur


- | | |
|---|---|
| <p>1. Name of the Officer</p> <p>2. Location</p> <p>3. Period for which the certificate is issued</p> <p>4. Types of building</p> <p>5. Nature of defect if any</p> <p style="margin-left: 20px;">a) Foundation and basement</p> <p style="margin-left: 20px;">b) Superstructure</p> <p style="margin-left: 20px;">c) Doors and windows</p> <p style="margin-left: 20px;">d) Wood work wrought and put up</p> <p style="margin-left: 20px;">e) Roof</p> <p style="margin-left: 20px;">f) Flooring</p> <p style="margin-left: 20px;">g) Miscellaneous (Cracks if any)</p> <p>6. Any Major defects notices which will render the building unsafe in any manner</p> <p>7. Whether maintenance works have been done properly</p> <p>8. Whether the structure is sound or not for conducting classes</p> | <p>: Seema.T.S</p> <p>: Kuriachira</p> <p>: 2024-'25</p> <p>: Permanent multistoreyed building</p> <p style="margin-left: 40px;">1) 1344.11m²</p> <p style="margin-left: 40px;">2) 2232.75m²</p> <p style="margin-left: 40px;">3) 403.92m²</p> <p style="margin-left: 40px;">NIL</p> <p style="margin-left: 40px;">[Fitness not issued for the third floor of 2232.75m² area building and for the first floor of 403.92m² area building]</p> <p>: NO</p> <p>: YES</p> <p>: The structure is sound for conducting classes under normal weather conditions</p> |
|---|---|

Note:- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

CERTIFICATE

Certified that the School was inspected by me on 01/07/2024
and found to be fit / unfit to conduct classes for the period 2024-'25
for the reason stated above.

Place: Thrissur
Date: 06/07/2024



Seema

Assistant Engineer
സീമ. റ്റി.എസ്.
അസിസ്റ്റന്റ് എഞ്ചിനീയർ
തൃശ്ശൂർ കോർപ്പറേഷൻ
K.J. Benny
Principal
ST. PAUL'S PUBLIC SCHOOL
KURIACHIRA, THRISSUR-6.

Manager
St. PAUL'S PUBLIC SCHOOL
KURIACHIRA